



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.10R

08/09/2012

Updates from previous versions:

Bug Fixes:

1. Sensor names have been changed from TI 200, 500 & 667 to MCS 200, 500 & 667. (T-150 & TI-150A stay as TI).

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.