



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 9.11F 10/30/2012

Updates from previous versions:

Bug Fixes:

1. Fixed the issue of not being able to change set point #1 from either the Magnum or MCS Connect.

RTU ONLY:

2. RTU has been corrected to handle the economizer AO properly. It was being set to zero opening if the building control option was not used.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.