



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.13V

08/22/2013

Updates from previous versions:

Bug Fixes:

1. The issue with tandem EXV on recip compressors down being handled correctly during pump down has been corrected. Screw compressors did not have this issue.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.