



SOFTWARE RELEASE NOTES

MCS-MICROMAG Version 14.00G & H 06/04/2013

Updates from previous versions:

Bug Fixes:

G:

1. When compressors were set to rotate, first compressor was not rotating properly. Also, heating did not have rotation. Resolution: Added rotation to heating, and initialized the rotation allowed flag to TRUE for both cooling and heating.

H:

1. Alarm info pointer was not showing up correctly when in internal alarm position 100. Resolution: Fixed overflow error. Alarm info pointer now shows up correctly.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.