



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 14.00I

06/17/2013

Updates from previous versions:

New Features:

1. Saved BMS Run/Stop and BMS Occupied mode through power fail
2. Added support for number of boards
3. Added Single Zone VAV options

Bug Fixes:

1. Updated a setpoint name -- LEAD COMPRESS to LEAD COMP
2. Properly initialized unload all comps before start next comp setpoint to FALSE
3. Changed Chiller Setpoint Names.
4. Changed names for setpoints 33 and 34.
5. Added a heater fault SI name.
6. When Config is invalid, allowed user to change 232 baud rate.
7. Added BMS interfacing with Single Zone VAV.
8. Fixed the cooling enable setpoint not displaying when hitting the left button on the keypad in the status menu.
9. MSVs were not implemented according to the BACnet standard. Resolution: Incremented the state values, and gave a segmentation not supported error when a BACNET_ARRAY_ALL was requested in state names.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.