



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 15.00F

07/25/2013

Updates from previous versions:

New Features:

1. Allowed Economizer "MIN DAMPER %" Setpoint (setpoint 22) to be written in BMS.

Bug Fixes:

1. Various minor keypad display and navigation improvements, including flash rate.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.