



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 15.00M

09/12/2013

Updates from previous versions:

New Features:

1. Setpoint 104 (Morning Warmup Time) now looks at the setpoint display type to determine how long to go into morning warmup for.

Bug Fixes:

1. MicroMag was not transmitting correct length to MCS-Thermostat, causing MCS-Thermostat to not receive occupied mode bits correctly. Resolution: Added two bytes to MCS-Thermostat message length to compensate for new byte alignment.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.