



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 15.00Q

11/20/2013

Updates from previous versions:

New Features:

1. Added a warning setpoint type
2. If the ignition safety setpoint is a warning setpoint type, only give an alarm for ignition fault.
3. Added 2 new SI names called Hw EntTemp and Hw EntHumd for AAON configurations.
4. Allowed users to adjust warning setpoint types from the keypad.
5. Added 4 new generic Temperature SI names called Temp 1, Temp 2, Temp 3, and Temp 4 for AAON configurations.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.