



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 15.00U

12/20/2013

Updates from previous versions:

New Features:

1. Added a 'compressor in defrost' status flag.

Bug Fixes:

1. Condenser Fan logic was not reversing when unit went from Heat Pump to Evap Fan Only and back to Heat Pump. Resolution: Rewrote reversing valve position logic to continuously set the condenser fan logic direction.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.