



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 15.01J

02/18/2014

Updates from previous versions:

Bug Fixes:

1. Capacity control did not set adjust delay value to 0 automatically when a unit began staging.
Resolution: When a unit is in post-staging delay, set the adjust delay value to its maximum.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.