



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 16.04I

02/03/2015

Updates from previous versions:

Bug Fixes:

1. Prevent Capacity Control from turning on a stage when conditions call for a decrease in capacity.
2. Correct check for condenser AO starting stage to ensure the Condenser Fan AO gets set properly.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.