



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 18.00E

10/23/2017

Updates from previous versions:

New Features:

Bug Fixes:

1. On chiller, when there is a no flow alarm the pump wasn't stopping. to fix it add disable_evap_run_stop_chiller function when the no flow is tripped.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2017. Copying or distributing this document is prohibited unless expressly approved by MCS.