



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 3.01K

11/16/2012

Updates from previous versions:

New Features:

1. Added UI for Precooling
2. Added a freeze lockout
3. Added precooling to keypad UI

Bug Fixes:

1. Fixed condensers not shutting off when unit is in lockout
2. Made cmp shutdown require a third input called cmp index
3. Ensured only one stage could be added at a time (fixing heating supervisory staging in the process)

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.