



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 4.00C

12/21/2012

Updates from previous versions:

New Features:

1. BACnet is updated to include all the new features
2. If the TRIAC is in manual or the digital scroll is running, 0% on the AO will now make the TRIAC unload 100% of the time, which is opposite of its previous behavior
3. Return Damper and Return Bypass Damper logic is included

Bug Fixes:

1. Supervisor Logic merged cooling and heating stage SIs. Stages will signify heat if the heat enable DI is on.
2. Supervisor Logic merged reheat demand and enable SIs. If reheat SI is below 1%, reheat is not wanted, otherwise reheat is wanted and demand is reheat SI.
3. History Head and Tail pointers no longer clear themselves out if they are too large
4. Relay Cycles were being stored incorrectly, this is resolved
5. Various new names and changes to names

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.