



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 4.00D

01/03/2013

Updates from previous versions:

Bug Fixes:

1. Changed name length definitions to include the new names.
2. Removed two particularly long (unused) "out string" messages to conserve space.
3. Fixed reheat staged reheat valves on with bypass.
4. Fixed return bypass and damper not modulating properly if reheat flush cycle isn't set up.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.