



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 4.00J

01/21/2013

Updates from previous versions:

New Features:

1. Added compressor state to represent off due to dehumidification

Bug Fixes:

1. Not all instances of aux_min_max were checking for the setpoint to be active. Resolution: Checked that the setpoint was active before using it
2. When unit was going to lost IO, active stages were not being decremented properly Resolution: Pulled and pushed the compressor variables after the shutdown

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.