



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 4.00N

01/25/2013

Updates from previous versions:

Bug Fixes:

1. When Heat Pump goes to defrost and condenser target changes, when heat pump leaves defrost, condenser target does not change back. Resolution: Verified all other possible condenser target offsets at the same time as defrost condenser target offset.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.