



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 4.00P

03/22/2013

Updates from previous versions:

Bug Fixes:

1. High Supply Temperature would lockout heating on first run, however other states were resetting it
Resolution: Implemented lockout delay and safety down time for High Supply Temp, also eliminated all overwrites of lockouts
2. Some unoccupied offsets were being implemented even if the setpoint was inactive
Resolution: Made a check whether these unoccupied offsets were active, and if not, set it to 0
3. When there is no heat pump, primary heating is displayed as aux and aux heating is displayed as emergency
Resolution: Added in RTU states for heating with primary
4. Certain configurations caused supervisor mode to inadvertently activate
Resolution: Ensured that only configurations configured for supervisor enabled supervisor mode

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.