



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 4.00S

04/05/2013

Updates from previous versions:

Bug Fixes:

1. In setpoint 49 (Compressor Adjust Delay), made a check on the setpoint type. If the setpoint type is not a minimum capacity setpoint, used 5% as default, otherwise used the minimum capacity setpoint as the adjustment %. This eliminates the previous logic of relying on the compressor minimum adjust %.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.