



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 4.00U

04/26/2013

Updates from previous versions:

New Feature:

1. Added Hood On. This switch will turn the economizer damper to its maximum position while the switch is active.

Bug Fixes:

1. Previously, the unit was checking whether the evap coil temperature was less than the defrost termination temperature to disable defrost. Resolution: The unit now ensures that the evap coil temperature is greater than the defrost termination temperature.
2. When in forced mode and staging and user wants reheat, logic was not turning on any reheat valves. Resolution: When in forced mode and staging, made stages wanted equal to compressors on. Also made supervisor reheat demand an integer.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.