



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.01E
01/15/2014

Updates from previous versions:

New Features:

1. Added an Information header above the lockout alarm info grid print as well as listing the name and time of the alarm.

Bug Fixes:

1. In MicroMag Evap Grid the "Target" and "Control On" columns were displaying incorrect info when not in cooling /heating mode. RESOLUTION - Checking setpoint #14 to determine if values should be shown in these columns or not.
2. Removed the timer above the menu bar on the Main User Interface as it was not being used for anything.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.