



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 14.01G
02/24/2014

Updates from previous versions:

New Features:

1. Added new state to V14 Chiller Circuit state array. "CMP GROUP OFF "
2. Finished new XML Graphic package - Package not used currently due to no graphics package in production for this feature.

Bug Fixes:

1. The lockout alarm history popup in V14 was incorrectly displaying the RO columns due to an incorrect index into the # of compressor stages. RESOLUTION - Fixed the index to get the correct circuit in order to get its correct # of stages.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.