



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 9.030
09/10/2012

Updates from previous versions:

Bug Fixes:

1. SI Filter Popup was being displayed off the viewable screen due to a bug that was determining the location of the SI Grid incorrectly. This caused any popup created AFTER the SI Filter popup to not display due to the constraint of only 1 popup at a time being allowed. Resolution - I changed the location of the SI Filter popup to be based on the center of the screen.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.