


## **APPLICATION NOTE**

## **APP120**

# WIRING MCS-050-DIFFB TRANSDUCERS USING PACK-CON-XX CABLE



#### Wiring to the Controller

MCS-PAC-CON-XX Connector	WIRE	Sensor Signal
PIN A	BLACK	GROUND
PIN B	RED	+5VDC
PIN C	WHITE	SI



### NOTICE:


If the sensor is replacing an older version (MCS-050-DIFF) a wiring change may be necessary as shown on left.

SEE MOUNTING INSTALLATION FOR MCS-050-DIFF TRANDUCER
ON NEXT PAGE


## **INSTALLATION**

Below shows the proper mounting of trhe MCS-050-DIFF in a Horizonial postion.

Pressure Connections - NPT1/4(female



Illustrations below show the proper mounting using the optional BRACKET, not included.



Any questions regarding this release, contact: support@mcscontrols.com