



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 17.00P 02/25/2015

Updates from previous versions:

New Features:

1. In ALL config types V14 and V17 on the Setup screen Default LCD Display drop down list adding a new Default called NO KEYPAD/DISPLAY which indicates to the Magnum to not communicate to a Keypad LCD.

Bug Fixes:

1. In HVAC and CENT config types V17 on the MAG Info screen under the CPM Info section on the Relays panel the Chiller Isolation Valve RO is being set back to 255 when the Chiller Condenser Isolation Valve RO is set from a point to Not Used. Resolution: In the YES/NO radio button event the values were being flipped on load. Reversed the memory locations.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.