



SOFTWARE RELEASE NOTES

MCS-CONFIG **Version 18.00E** **5/31/2016**

Updates from previous versions:

New Features:

1. In ALL config types V17 that utilize the Circuit Base screen on the third grid from the top under the Evaporator EXV Control column adding a new control state called SSH PID.
2. In ALL config types V17 that utilize the Circuit Base screen on the third grid from the top under the Evaporator EXV Control column adding a new control state called Fast SSH.
3. In ALL config types V17 on the SI Info screen under the Display Type column adding 3 new sensor types called DB_CENT_SIMN_FLT_1, DB_CENT_SIMN_FLT_2, DB_CENT_SIMN_FLT_3 and will be saved as 169, 170, 171. Also, with this change there will be 50 alarms added to the BMS Points alarms list.

Bug Fixes:

1. In ALL config types V8 on the MAG INFO screen on some display adapters there is an error #380 shown when opened. Resolution: Move the resize of the scroll bars function that is assigning a negative value to the SmallChange property.
2. In HVAC config types on the Circuit SI screen on the second from the top grid under the Leaving Temp column the Tooltip and Header click are showing the incorrect Setpoint#. Resolution: In the HeaderClick and MouseHover sub routines change the setpoint#.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2016. Copying or distributing this document is prohibited unless expressly approved by MCS.