



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 18.01C 11/16/2017

Updates from previous versions:

Bug Fixes:

1. In ALL cfg types V17 on the SI Info screen under the Display Type column when the type is CARR-5K the index that is being saved is a 57 instead of a 122. Resolution: There were 2 instances of this type in the Display Type list. Made the instance of 57 what it used to be which was MOTOR_TEMP.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2017. Copying or distributing this document is prohibited unless expressly approved by MCS.