



SOFTWARE RELEASE NOTES

MCS-CONFIG **Version 18.01E** **04/24/2018**

Updates from previous versions:

Bug Fixes:

1. Bug Fix: In ALL config types V17 that support the BMS Points screen under the Alarms section under the Fixed Alarms Type # 11 Point Number is Not Used (255) and should be STPT #. Resolution: Add another test for #11 to change the value of that row.
2. In ALL config types V11 and V14 that support the circuit base screen the condenser grid is not loading correctly when opened. Resolution: Created static column index variables to separate V11 and V14 column index variables from V17 column index variables.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2018. Copying or distributing this document is prohibited unless expressly approved by MCS.