



SOFTWARE RELEASE NOTES

MCS-CONFIG **Version 18.01L** **02/07/2018**

Updates from previous versions:

Bug Fixes:

1. In HVAC, CENT, MHRC, REFR, and RTU config types on the MAG INFO screen under the Evaporator/Cooling Info section on the EXV Control panel the YES/NO option is setting setpoint #9 SEC to Ignore Safety column to a 1 for YES and a 0 for NO which is causing an issue with new PID Magnum logic. Resolution: In the click procedure of the YES/NO options adding a test to make sure the setpoint type for setpoint #9 is not a target and the Evaporator EXV Control is not set to any of the PID types on the Circuit Base screen.
2. In ALL config types V17 on the SI Info screen under the Display type column when the type selected is Lookup Table and the Lookup Table Wizard form loads the Operand Type field is causing an error OnLoad. Resolution: Added out of bounds tests to the memory location for the Operand Type and the Secondary Display type.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2018. Copying or distributing this document is prohibited unless expressly approved by MCS.