



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 8.00J 03/22/2011

Updates from previous versions:

New Features:

1. New Lockout logic has been added allowing the user to select which compressors will be Locked Out when communications with a particular I/O board is lost. A new option has been added in the MAG V8 screen to access the panel to configure how to Lockout. Requires HVAC software version 8.05-C or newer.

Magnum HVAC V8 Information Screen

Information Panel Selector

☐ General Info ☐ Compressor Info ☐ Evaporator Info ☐ Condensor Info ☐ **Lockout Info** ☐ Boiler Info

Lockout Information

Enable locks based on Boards?
☐ Yes ☐ No

This screen allows the user to set up which compressors to lock out after a loss of communications to the I/O boards.

	R010 #1	R010 #2
No Lockouts	☒	☐
Lockout Chiller	☐	☐
Lockout Comp #1	☐	☒
Lockout Comp #2	☐	☒
Lockout Comp #3	☐	☒
Lockout Comp #4	☐	☒

	SI16 #1	SI16 #2
No Lockouts	☒	☐
Lockout Chiller	☐	☐
Lockout Comp #1	☐	☒
Lockout Comp #2	☐	☒
Lockout Comp #3	☐	☒
Lockout Comp #4	☐	☒

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.