



SOFTWARE RELEASE NOTES

MCS-CONFIG Version 9.03L 05/24/2012

Updates from previous versions:

Bug Fixes:

1. On the RTU MAG info screen, under the general section on the occupied indicators panel, the caption "Schedule?" was changed to "Use Operating Schedule As:". Also, the radio selection "Yes" and "No" were changed to "Night Setback" and "On/Off".
2. On the RTU MAG info screen, under the ventilation section on the building PSI Control panel, when the user clicks on the "Not Used" control method setting, the following bytes are set:
 - a) Building Static PSI byte
 - b) Exhaust fan relay byte
 - c) Exhaust fan AO byte
 - d) Exhaust fan speed fault byte
 - e) Exhaust fan vfd bypass byte
3. On the SI Info Screen, the Manual Value column and the Auto/Manual column change now only when the user clicks the button in the cell and not just anywhere in the cell.
4. On the SI Info Screen, the Auto/Manual column, when the header is clicked and the user clicks the button that sets all sensors to Manual changing the function of this button to only set the active SI's to manual. This will also be the same for the active SI's that show as a Spare.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.