

TONTROL SOFTWARE RELEASE NOTES

MCS-CONNECT Version 17.00K 01/09/2015

Updates from previous versions:

New Features:

1. Added AO Modbus Write User Interface for new AO type "Modbus Write".

Bug Fixes:

- 1. In the User Defined SI Cell Editor's SI Filter Digital Popup Connect was setting the value of the Display text incorrectly when the user selected the "Yes, No" option. If this option was selected the Si Grid would display "Unknown" as Connect was changing the saved value to 255. This was supposed to be done with the "NO or NC" drop down instead. RESOLUTION Changed the test to the correct combo box.
- 2. In V17 the Service Panel is not being completely initialized due to lack of a check for V17 config type.

Any questions regarding this release, contact: <u>support@mcscontrols.com</u>

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905 (239)694-0089 FAX: (239)694-0031 <u>www.mcscontrols.com</u>

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.