



SOFTWARE RELEASE NOTES

MCS-CONNECT
Version 17.14.05
05/02/2016

Updates from previous versions:

New Features:

1. Added support for making the background image of a button transparent in graphics.
2. Added support for transparent buttons to Offline Graphics class.
3. Added 3 new SI types "DBCENT_FLT1", "DBCENT_FLT2", "DBCENT_FLT3".
4. Added support for display Type 0 Compressor relays to display a FLA popup to allow users to edit EXV and starting compressor values.

Bug Fixes:

1. Increased the # of retries before popping up with a lost communication message from 6 to 12 for serial communication.
2. Due to a config error the Auxiliary heating grid printing code is being run when no grid is present.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2016. Copying or distributing this document is prohibited unless expressly approved by MCS.