

TONTROL SOFTWARE RELEASE NOTES

MCS-CONNECT Version 14.00I 06/28/2013

Updates from previous versions:

New Features:

- 1. Added EXV States into the data that is exposed to the Graphics screen. Gave it an id of "XV:circuit#".
- 2. Added registered function calls to Graphic HTML Loader as a framework to give the user the ability to change Sensor values from Graphics.
- 3. Added a registered function to Graphic HTML Loader to allow the user to do a lockout reset from a button in Graphics even though there is a menu item already in place.

Bug Fixes:

- 1. In Magnum V14 the alarms had not been updated to take into effect the expanded setpoints. RESOLUTION Made the function in Magnum V14 Device match the V14 SW.
- 2. V14 configs were unable to display graphics causing MCS-Connect to lock up when attempting to load the embedded browser. This was due to MCS-Connect attempting to use the same split up path name as V11 uses. In V14 we consolidated it to be just one field in System Graphic V14 memory location. RESOLUTION Made the routine to get the system graphic file name for V14 look at the correct class member like the MicroMag does.

Any questions regarding this release, contact: support@mcscontrols.com