



SOFTWARE RELEASE NOTES

MCS-CONNECT **Version 18.19.14** **05/17/2018**

Updates from previous versions:

New Features:

1. Check for Transmit firmware Acknowledgment to add the status flag to the checksum for the new bootloader.
2. Circuit number to all the miscellaneous alarms shown in the Alarm Grid.
3. Process Pump control grid feature to MicroMag V18.
4. A code to fix the issue with loading offline graphs and having grids in the setup popup load blank point names.

Bug Fixes:

1. The CPM target column is displaying the value incorrectly if the sensor is User defined.
2. Changed the Extended Lockout history pullback functionality to allow for cancelling of the pullback without blowing up connect.
3. Reduced the number of Max extended alarm info records allowed from 15 to 10.
4. Increases the numbers in the Service Panels MCS address combo box from 20 to 99.
5. Edited the Extended history popup message for clarity per BWW.
6. Fixed an error in the CPM alarm grid when displaying the emergency stop alarm.
7. Edited the Extended history popup to display the correct ACU states for compressor and circuit tabs.
8. The test for Large device type before initializing the Service grid was using the incorrect device index variable.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2018. Copying or distributing this document is prohibited unless expressly approved by MCS.