



RELEASE NOTES

MCS-CONNECT Version 9.03 L & M 09/10/2012

Updates from previous versions:

L

New Features:

1. Adding new fields to AO memory.
2. Adding new fields to Machine memory.
3. Adding new setpoint type to V12 config types.

Bug Fixes:

4. Alphabetizing the SI Types drop down in all Device types.
5. MCS-8 PET code was hanging when loading MCS-8 config due to the circuit and exv classes not being initialized.
6. Created new Service Panel V12 for the MicroMag.

M

Bug Fixes:

1. AOs incorrectly indexed in Graphics Loader.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.