



## RELEASE NOTES

---

# MCS-CONNECT Version 9.03N, O, & P 09/10/2012

### Updates from previous versions:

## N

### New Features:

1. Adding new compressor state to HVAC SW - ON OIL RECOVERY (40)
2. Adding a new condenser level control type to determine if Variable orifice exists.
3. Adding check for ACU SW to Serial Scan Initialization state in Information Thread.
4. Adding new fields to Machine memory to enable Extended Bacnet ID.

## O

### Bug Fixes:

1. SI Filter Popup was being displayed off the viewable screen due to a bug that was determining the location of the SI Grid incorrectly. This caused any popup created AFTER the SI Filter popup to not display due to the constraint of only 1 popup at a time being allowed. Resolution - I changed the location of the SI Filter popup to be based on the center of the screen.

## P

### New Features:

1. Adding new mod gas heating grid to Micro Mag code.
2. Added tool tip text to information grid.
3. Changed headings of variable orifice states.

Any questions regarding this release, contact:  
[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.