



# SOFTWARE RELEASE NOTES

---

MCS-CONNECT  
Version 9.03R  
09/17/2012

## **Updates from previous versions:**

### **New Features:**

- 1. Adjusting setpoint type "time" to match micromag - adding 2 new columns to setpoint grid.**

### **Bug Fixes:**

- 1. Timeout pop up to automatically shut MCS-Connect down after a period of inactivity. Resolution - Added an option to the Communication Setup to allow users to enable/disable timer and set value of # of minutes of inactivity before shutdown timeout.**
- 2. In the Micro Mag - Rate of Change field was getting incorrect decimal place values. Resolution – Corrected the algorithm.**

Any questions regarding this release, contact:  
[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

**Micro Control Systems, Inc.** 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.