



SOFTWARE RELEASE NOTES

MCS-MAGNUM
Version 14.01Q
10/09/2013

Updates from previous versions:

New Features:

1. New sensor added for with 1 decimal tons.

Bug Fixes:

1. Correction to the split compressor logic, if compressors available are not sufficient turn off compressors in the suction group.
2. All versions now use a common function for the condenser control.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.