



SOFTWARE RELEASE NOTES

MCS-MAGNUM Version 14.01Z 12/23/2013

Updates from previous versions:

New Features:

ALL:

1. Added limit of daily lockout resets when using the lockout reset sensor input.

Bug Fixes:

All software that supports EXV:

1. Updated to handle Hanbell Fixed step compressors.
2. To indicate that EXV adjustments should be made based upon the percentage cell in the RO information screen either in the compressor or if unloader is the first unloader.

REFR:

3. Updated to match V9 changes.

RTU:

4. When switching between modes and the wanted/actual on was 1/0 the unit would wait until this changed. Corrected this issue.
5. The outside air damper maximum setting will be value in set point MAX ECON VALUE. The CFM logic was letting it go to 100%. We moved from economizer state to mechanical cooling which caused issues.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.