



SOFTWARE RELEASE NOTES

MCS-MAGNUM **Version 17.14D** **03/09/2015**

Updates from previous versions:

New Features:

1. LWC, correct staging delay-Now uses set point for fine adjustment.
2. HVAC/Boiler pump logic: Second boiler pump is not coming ON. Pump #1 comes on AO modulates from minimum to maximum and logic stays stuck at 1/1/2.
3. Improvements to new disable keypad/LCD display communication option: Added logic to allow end user to enable or disable option from MCS-Connect.
4. LCD communication timer was not been reset correctly after re-establishing communication.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.