



SOFTWARE RELEASE NOTES

MCS-MAGNUM **Version 17.14I** **04/7/2015**

Updates from previous versions:

Bug Fixes:

1. Prevented condenser ROs from being initialized to on rather than off
2. Bug Fix: Allowed boiler pumps to stage up and down properly when boiler pump is not "always on"
3. Bug Fix: Allowed boiler pumps to stage down to 0 stages when boiler pump is not "always on"
4. Corrected the issue with boiler stages in the HVAC software.

Any questions regarding this release, contact:
support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.