



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 17.21F

12/01/2015

Updates from previous versions:

Bug Fixes:

1. HVAC - Set compressor speed AO to 0 when recip or mitsubishi circuit is off and HGB is not modulating.
2. REFR V17, all changes from V16 have been moved into V17. This should be used for all future REFR jobs.
3. CPM: Make CPM state timer max out at 255 hours on display.
4. Fixed bug preventing Ethernet Ports other than 5000 from working. Also prevented ethernet processing while in WRITING_CFG state.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.