



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.01E

11/29/2011

Updates from previous versions:

Bug Fixes:

1. Fixed the R113 conversion from pressure to temperature that was calculating incorrectly for negative values.

CENT SOFTWARE ONLY:

2. Changed the purge mode switch logic so that the purge enable RO is on if mode is in MANUAL or AUTO and the compressor is on. (Previously the purge suction temperature also had to be less than setpoint #163 "PURGE TARGET" before the purge enable RO was turned on). The purge solenoid RO and the purge exhaust fan are still controlled by the purge suction temperature.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.