



SOFTWARE RELEASE NOTES

MCS-MAGNUM

Version 9.01F

11/29/2011

Updates from previous versions:

Bug Fixes:

HVAC SOFTWARE ONLY:

1. Changed the pumpdown state logic. Now the compressor will not load when in pumpdown, it will stay unloaded (the unloader relay will stay on, loader relay will stay off).

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2012. Copying or distributing this document is prohibited unless expressly approved by MCS.