



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 14.00J

06/26/2013

Updates from previous versions:

New Features:

1. Added Alarms to MSVs in BACnet and Modbus.
2. Changed Supervisor State Names.
3. Removed option for Network Forced Mode and Network Forced Mode and Staging, as they were redundant.
4. Added Supervisory Forced Mode
5. Added an SI name, COOL ENB

Bug Fixes:

1. Setpoint menu would default to setpoint 1 rather than the first active setpoint. Resolution: Made menu go to first active setpoint when entering setpoint menu.
2. When unit was in forced mode and staging, the no flow alarm would not turn on. Resolution: The no flow alarm now turns on when the unit is in forced mode and staging.
3. Uninitialized history pointers in RTC ram combined with signed integers were causing configurations to be destroyed. Resolution: Changed history head and tail pointers to be unsigned, causing the check for pointer value to evaluate properly.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.