



# SOFTWARE RELEASE NOTES

---

## MCS-MICROMAG

## Version 15.000

## 10/08/2013

### Updates from previous versions:

#### New Features:

1. Now allowing the user to change trip delay field in configs if the time allowed.

#### Bug Fixes:

1. Holding registers were not responding to the correct address. Resolution: Shifted all non-AO Modbus holding registers up an address.
2. Write Single register command was giving an improper address exception when a device tried to write to a valid, but out of range register. Resolution: Forced Modbus to give a negative acknowledge if the data value is out of writable range.
3. Allowed High Ambient Off Temp setpoint to disable heating even if unit is in Forced Mode and Staging.

Any questions regarding this release, contact:

[support@mcscontrols.com](mailto:support@mcscontrols.com)

---

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905  
(239)694-0089 FAX: (239)694-0031 [www.mcscontrols.com](http://www.mcscontrols.com)

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.