



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 15.01G

01/20/2014

Updates from previous versions:

Bug Fixes:

1. Ensured that heating fixed stages came on appropriately. Previous version did not catch every fixed heating stage case.
2. Fixed issue with Hood On Switch causing the mode enable SI to be set improperly when the switch turns back off.
3. Mod gas valve AO now checks whether the AUX HEAT MIN/MAX setpoint is active.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2014. Copying or distributing this document is prohibited unless expressly approved by MCS.