



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 16.04H

02/03/2015

Updates from previous versions:

New Features:

1. Added new unloader RO names to Chiller ROs.
2. Added new RO names for Unloaders to AAON, SKM and uMag software.

Bug Fixes:

1. Ensure that check for bypass condenser checks the variable, rather than the pointer.
2. When compressor with unloader was OFF, the unloaders relays were set to ON, causing the relays to cycle ON and OFF. Resolution: By keeping unloaders relays off when compressor is OFF.
3. Completed implementation for Scroll Compressor with Unloaders and added new names for Chiller ROs to all Software. (uMag, SKM and AAON)
4. Ensure that condenser starts at the correct AO% when condenser minimum % setpoint is active.

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2015. Copying or distributing this document is prohibited unless expressly approved by MCS.