



SOFTWARE RELEASE NOTES

MCS-MICROMAG

Version 4.00K

01/23/2013

Updates from previous versions:

New Features:

1. Added new SI names for compressor proofs

Bug Fixes:

1. Supervisor Cooling stopped working on the merge between cooling and heating. Resolution: Modified supervisor cooling to properly read the stages
2. Supervisor Forced Mode and Staging -- Heating with modulating gas cycled an extra stage if modulating gas was above the "GAS_MAX_PERCENT_BEFORE_LAST_STAGE" definition. Resolution: Ignored the GAS_MAX_PERCENT_BEFORE_LAST_STAGE definition during forced mode and staging supervisor mode.
3. "Low Oil PSI" alarm was changed to "LOW PSI DIFF"

Any questions regarding this release, contact:

support@mcscontrols.com

Micro Control Systems, Inc. 5580 Enterprise Parkway Fort Myers, Florida 33905
(239)694-0089 FAX: (239)694-0031 www.mcscontrols.com

Information contained in this document has been prepared by Micro Control Systems, Inc. and is copyright © protected 2013. Copying or distributing this document is prohibited unless expressly approved by MCS.